



ISUZU JUSTON
Stock ID 139875

Registration Year: 1998
Manufacture Year: 0

Vehicle Specifications

| | | | | | | | |
|----------------|------|-----------------|-----------------|-------------|-------------------|-----------|--------|
| Model: | | Chassis No: | NRR33D4-3000226 | Grade: | | Fuel: | Diesel |
| Engine: | 6HH1 | Drive Train: | 2WD | Dimensions: | 32 M ³ | Shape: | DUMPER |
| Engine No: | 2023 | Transmission: | MT | Mileage: | 374300 | Capacity: | 8220cc |
| Ext. Color: | | Weight (kg): | | Seats: | 3 | Color: | |
| Certification: | | Classification: | | Exterior: | WHITE | Interior: | GRAY |

Vehicle images



Vehicle Options

| | | | | | | | |
|---------------------|-----|-------------------|-----|-----------------|------------------------|----------------|-----|
| Pwr Steering | Yes | Pwr Wind | Yes | Pwr Mirrors | Center Lock | Air Cond | Yes |
| Reverse Camera | | Pwr Slide Door | | Easy Closer | Cruise Control | ABS | |
| Air Bag | | Fog Lamps | | HID Head Lamps | LED Head Lamps | Spare Key | |
| Remote Key | | Push Start | | Seat Heater | Pwr Seat | Leather Seat | |
| Floor Mat | | Sun Roof | | Alloy Wheels | Grill Guard | Rear Wiper | |
| Rear Spoiler | | Stereo (FULL) | | Navi/TV | CD Player | Car MD | |
| AUX | | Spare Tire | | Spare Tire Case | Puncture Repairing Kit | Tool | |
| Jack | | Operators Manual | | Maint. Record | 360 Degree Camera | AM/FM Radio | |
| 4WD | | 2WD | Yes | Back Tire | TV | Body Kit | |
| Side Skirts | | Front Lip Spoiler | | Turbo | Side Airbag | Wheel Spanner | |
| ESC | | Keyless Entry | | Front Airbags | Climate Control | Premium Lights | |
| Premium Wheels/Rims | | Premium Paint | | Racing Seats | Performance Tyres | | |

